



Dominion

DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DATE: JAN. 19, 2016

WEATHER: 19°F ; SUNNY

INSPECTED BY: K. ACRE

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	1040 SAND BAGS + RIPRAP IN PLACE AND NO STANDING WATER AGAINST SAND BAGS
Erosion	N	N	SEVERAL SAND BAGS ARE RIPPED
Low Point, B dike*			
Flow	N	N	1013 SAND BAGS ARE IN PLACE AND THERE IS NO STANDING WATER AGAINST SAND BAGS
Erosion	N	N	SEVERAL SAND BAGS ARE RIPPED
Outfall			
water surface El. (top of stoplogs to water)			10:30 NO STANDING WATER AGAINST WEIR AND WEIR IS DRY

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): - LOW POINT, C DIKE -> SAND BAGS ARE IN PLACE, THERE IS NO STANDING WATER AGAINST SAND BAGS, AND SEVERAL SAND BAGS ARE RIPPED
 - SEVERAL AREAS WHERE STANDING WATER IS AT TOP OF EMBANKMENT, AS NOTED BELOW.
 - STANDING WATER AT TOP OF POND C EMBANKMENT, WITHIN POND. (TYPICAL OF ~~DIFF~~ ^{A+B} PONDS)

